

Outgoing
00070020

Page 1 of 1

R

Suzanne Steab - August 2011 Inspection Report

From: Karl Houskeeper
To: kit@emerytelcom.net
Date: 9/15/2011 1:57 PM
Subject: August 2011 Inspection Report
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: Horizon August 2011.pdf

Kit,

Attached is the August 2011 inspection report for Horizon.

Thanks,
Karl



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070020
Inspection Type:	COMPLETE
Inspection Date:	Thursday, August 11, 2011
Start Date/Time:	8/11/2011 9:30:00 AM
End Date/Time:	8/11/2011 1:30:00 PM
Last Inspection:	Wednesday, July 20, 2011

Inspector: Karl Houskeeper,

Weather: Clear, Temp. 74 Deg. F.

Inspection ID Report Number: 2827

Accepted by: jhelfric
8/11/2011

Permitee: HIDDEN SPLENDOR RESOURCES

Operator: HIDDEN SPLENDOR RESOURCES

Site: HORIZON MINE

Address: 57 WEST 200 SOUTH, SUITE 400, SALT LAKE CITY UT 84101

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

1,577.00	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl H. Houskeeper

Date

Thursday, August 11, 2011

Karl Houskeeper,

Inspector ID Number: 49

Note: This inspection report does not constitute an official record of the Division of Oil, Gas and Mining. It is subject to review and modification by the Division of Oil, Gas and Mining. For more information, please contact the Division of Oil, Gas and Mining at (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070020
 Inspection Type: COMPLETE
 Inspection Date: Thursday, August 11, 2011

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS, PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/020 was issued effective 10/11/2006 and expires 10/11/2011.

-Certificate of Insurance policy number MNG880008-01 issued 06/04/2011 and terminates 06/04/2012.

-UPDES permit UTG040000 (General) UTG040019 (Site Specific) effective 05/01/2008 and expires midnight 04/30/2013.

-Air Quality permit DAQE-700-70, issued November 7, 2000.

-SPCC Plan dated January 2010. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number.

3. Topsoil

A thistle plant was observed on the topsoil pile located on the hill side next to the bath house. The plant should be removed and disposed of properly.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Second quarter 2011 sediment pond inspection was conducted on June 7, 2011.

4.e Hydrologic Balance: Effluent Limitations

The June 2011 discharge monitoring reports were reviewed. No parameters were exceeded.

16.a Roads: Construction, Maintenance, Surfacing

Off tracking onto the county road is evident. The material on the county road needs to be cleaned up.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-700-00 was issued on November 7, 2000. Recent documentation shows the approval order number as DAQP-002-06.

21. Bonding and Insurance

The bond is secured by a letter of credit through Bank One in the amount of \$57,000 and collateral to add up to the amount of \$342,000. This letter of credit expired on January 20, 2007. The appraisal was updated as of 12/20/06 for the real estate (collateral) and the appraisal is now \$625,000 and the collateral is adequate. The updated reclamation cost estimate is \$445,000 in 2011 dollars.